



**PANAMA MARITIME AUTHORITY
(AUTORIDAD MARÍTIMA DE PANAMÁ)
GENERAL DIRECTORATE OF MERCHANT MARINE
(DIRECCIÓN GENERAL DE MARINA MERCANTE)
DEPARTMENT OF CONTROL AND COMPLIANCE
(DEPARTAMENTO DE CONTROL Y CUMPLIMIENTO)**

F-265
(DCCM)
V.00



MERCHANT MARINE CIRCULAR MMC-238

To: Ship-owners/Operators, Company Security Officers, Legal Representatives of Panamanian Flagged Vessels, Panamanian Merchant Marine Consulates and Recognized Organizations (ROs).

Subject: Ship Protection Measures for Vessels transiting High Risk Areas.

**Reference: MSC. 1/CIRC. 1390
MSC. 1/CIRC. 1339
Merchant Marine Circular No. 206
Merchant Marine Circular No. 208
Merchant Marine Circular No. 228
Merchant Marine Circular No. 230
Merchant Marine Circular No. 245
Merchant Marine Circular No. 249**

1. The Administration urges Companies, Company Security Officers (CSO), Ship Security Officers (SSO) and Private Maritime Security Companies (PMSC) of Panamanian flagged vessels to implement the necessary security measures described in the latest edition of the Best Management Practices [BMP](#), before, during and after the transit through High Risk Areas.

2. The use of Best Management Practices must be reviewed and implemented by all the parties involved prior to entering high-risk areas. The implementation of BMP must include, but is not limited to the following:

- a) Conduct trainings / drills with the crew;
- b) Watchkeeping and Enhanced Vigilance;
- c) Effective use of monitoring and/or surveillance equipment;
- d) Maneuvering practice;
- e) Alarm or Alerts systems to demonstrate awareness to any potential attacker;
- f) Use of deck lighting and illumination to demonstrate awareness to any potential attacker;

- g) Denial of use of ship's tools and equipment, and protection of equipment stored on the upper deck;
- h) Control of Access to Bridge, Accommodation and Machinery Spaces and Physical Barriers;
- i) Other equipment used for self-defense; and
- j) Safe-Muster Points and Citadels, if determined appropriate.
- k) Submit vessel movements and transit plans to MSCHOA and all other organizations in the area before, during and after transiting High Risk Area.

3. The Ship-owners, Ship-operators, must make sure the crew is familiarized with all the recommendations given in the BMP and by this Administration. They must also communicate with crew relatives before entering High Risk Area in order to make them aware of the transit and must also provide them with the contact on the different organizations which operate in the area so they can communicate with these organizations in case there is a need to do so.

4. All the Private Maritime Security Companies (PMSC) listed in the MMC 245, must ensure compliance with Best Management Practices and coordinate with the master and crew that all exercises are planned and conducted on board prior to entering the High Risk Area and these measures must be kept before, during and after the transit.

5. All Panamanian flagged vessels whether using or not the services of Private Maritime Security Companies should maintain a wide communication with the Administration and to liaise with the International Contact Centers according to the BMP in order to counter piracy in the High Risk Areas of the Gulf of Aden, Indian Ocean and any other Region of High Risk, as determined by this Administration before, during and after the transit.

For this reason, we strongly encourage all Panamanian flagged vessels to complete and submit the "Vessel Position Reporting Form" to UMKTO, and the "Vessel Movement Registration Form" to MSCHOA, both described in the latest edition of the Best Management Practices (BMP) prior to entering the High Risk Area, including the International Recommended Transit Corridor (IRTC).

6. All Panamanian flagged vessels transiting High Risk Area must make sure their LRIT System works properly at all times and must also report all their movements.

7. All inquiries concerning international correspondence must be sent to the Maritime Ship Security Department to the following e-mail address:

MARITIME SHIPS SECURITY DEPARTMENT

threat@amp.gob.pa

Monday to Friday

Phones (+507) 501-4224 / 5037 / 5028

SEGUMAR OFFICE

authorizations@segumar.com

Weekends and Holidays

Phones (+507) 501-5350 / 5348 / 5032

ABSOLUTE MARITIME TRACKING SERVICES, INC.

Phone (+507) 301-5748

Fax (+507) 301-5749

activations@absolutemaritime.com

July, 2018 – *Change in the hyperlink documentation of paragraph No. 1*

March, 2014 – *Addition of new paragraph in point 5*

August, 2013 – *Changes all throughout the text*

April, 2012

Inquiries concerning the subject of this Circular or any request should be directed to:

Directorate General of Merchant Marine

Panama Maritime Authority

Phone: (507) 501-5033

Fax: (507) 501-5083

PanCanal Building

Albrook, Panama City

Republic of Panama

Tel: (507) 501-5355 mmc@amp.gob.pa